


ANNEXURE

II

OFFICE OF
 THE CHIEF ARCHITECT,
 MAHARASHTRA STATE,
 P.W.D., MUMBAI.

REVISION	NO.	DATE	SIGN	CONTENTS

B.M. SANYAL (CA/190/12830)
 CHIEF ARCHITECT





FLOOR PLAN
TOTAL BUILT UP AREA = 1490.93 SQ.M.

NO. DATE
REVISION
OFFICE OF THE CHIEF
MAHARASH
P.W.D., MUN

B.M. SANGHVI (CA/190/12830)
CHIEF ARCHITECT

P.S. BALIWANT (CA/183/17574)
DY. CHIEF ARCHITECT

PROPOSED NERPHOL
KIDNEY TRANSPLANT U
G.M.C.H., AURANGABAD

WORKING DRAWING



शासकीय वैद्यकीय महाविद्यालय, औरंगाबाद

ईमेल : deangmca@gmail.com

पत्ता :- पानचवकी शेजारी, औरंगाबाद महाराष्ट्र 431001

अधिष्ठाता कार्यालय : 0240-2402028

कार्यालय : 0240-2402412

जा.क्र. शावैमओ/ ३९५ /2022

दि : २९/०४/२०२२

विषय :- नर्सिंग वसतीगृहातील विद्यार्थ्यांना इतरत्र स्थलांतरीत करणेबाबत . .

संदर्भ :- मा.सहसंचालक, वै.शि.व सं. मुंबई यांचे दुरध्वनीवरील आदेश दि २८/०४/२०२२

उपरोक्त विषयास अनुसरून कळविण्यांत येते की, मा.सहसंचालक, वै.शि.व सं. मुंबई यांनी दि २८/०४/२०२२ रोजी दुरध्वनीद्वारे कळविले की, मा.आयुक्त, वै.शि. यांची व प्राचार्य, नर्सिंग महाविद्यालय औरंगाबाद यांच्या झालेल्या बैठकीच्या अनुषंगाने नर्सिंग वसतीगृह जीर्ण झाल्याने विद्यार्थ्यांना इतरत्र स्थलांतरीत करण्याच्या सूचना दिलेल्या आहेत. त्याबाबत मा.अधिष्ठाता यांचयाशी चर्चा करावी तसेच महाविद्यालय परिसरात स्थलांतर योग्य जागा निवडून मा.अधिष्ठाता यांना अवगत करावे त्यानुसार तातडीने कार्यवाही करून विद्यार्थ्यांना इतरत्र स्थलांतरीत करावे.


(डॉ. वर्षा रोले)

अधिष्ठाता,

शासकीय वैद्यकीय महाविद्यालय व रुग्णालय,
औरंगाबाद

प्रति,


१. प्राचार्य, नर्सिंग महाविद्यालय शा.वै.म.औरंगाबाद
२. प्रशासकीय अधिकारी, महाविद्यालय, शा.वै.म.औरंगाबाद


29/04/22

आवक क्र - 46

22/7/2022

STRUCTURAL AUDIT REPORT



Ref. No. DIEMS/2022-2023/ 53

Date: 22/07/2022

PROJECT	STRUCTURAL AUDIT OF "GOVERNMENT NURSING COLLEGE, GHATI PARISAR, DIST- AURANGABAD.
CLIENT	DEAN, GOVERNMENT MEDICAL COLLEGE AND HOSPITAL, AURANGABAD-431005.
DATE OF AUDIT	06/06/2022 To 10/06/2022
REFERENCE	YOUR REQUIREMENT LETTER NO 1026/22 DATED 19/05/2022
STRUCTURAL CONSULTANT	DEOGIRI INSTITUTE OF ENGINEERING AND MANAGEMENT STUDIES, AURANGABAD.



MSPM'S
DEOGIRI INSTITUTE OF ENGINEERING AND MANAGEMENT STUDIES, AURANGABAD

Department of Civil Engineering,
Deogiri Institute of Engineering and Management Studies,
Deogiri Campus, Railway Station Road, Aurangabad
Maharashtra State, India.
Contact: +918087971768, 9822792354, (0240)02367544
Mail: info@diems.edu.in


[Handwritten signature]
22/7/22

7. CONCLUDING REMARK

From the test results & visual observations following conclusions can be arrived at:

- Corrosion in reinforcement is present in most of the tested members which is directly visible through major cracks and damages. Retrofitting of members with addition of new reinforcement will be advised if client is interested in restoring the structure. The strengthening and repair of the structure may require heavy treatment like steel jacketing, carbon fiber wrapping, steel girders, Micro-concrete / Polymer Mortar treatment which is quite expensive and time consuming. The leakage and seepage of rainwater in the structural components causes heavy corrosion of reinforcement.
- Almost in all places, rust removal treatment of existing reinforcement may advice. Members where addition of new reinforcement is required can be decided during repair works, once the corroded reinforcement is completely visible.
- Due to presence of corrosion, the surface concrete has deteriorated and hence the strength of surface concrete has become lower. Surface concrete will have to be repaired at all locations where distress has been observed. Distressed slabs should be attended on priority to prevent any mishap.
- Leakage through external wall, terrace and construction joints is observed on most of the places which results in severe damage to all structure. It is recommended that Re-plastering work to be done for whole building by using waterproofing compound.
- Almost all plumbing lines are damage / leaked & are causes of dampness / leakages at external as well as internal wall, it is recommended that need to be replace all plumbing lines.
- All the toilets must be reconstructed.
- Staircase required immediate repair work.
- The terrace water proofing is totally to be redone with proper slopes.
- New windows and protection grills to be installed.
- Entire building to be colored from outside and inside.

Based on the detail study of the structural and Non-structural members, it can be concluded that the BUILDING IS NOT STRUCTURALLY SAFE to occupy its intended purpose at present situation. Only after carrying out all the recommendations as listed above, the building can be strengthened. But strengthening of the building may require extensive repair work which may be expensive and time consuming.



Audit Committee Member	HEAD- CIVIL ENGINEERING DEPARTMENT	DIRECTOR- DIEMS
Sign:	Sign:	Sign:
Name: Prof. R. S. Patil	Name: Dr. Gajendra Gandhe	Name: Dr. Uhas Shiurkar

Disclaimer: 1. The Institute and concern staff member is not accountable or responsible for any objections/doubt/query in the report if client and/or intended user have not contacted them within seven days from the date of issue of the report. 2. The information furnished in this analysis report is solely for the intended user only and it is confidential as well as legally privileged. 3. The validity of this analysis report is limited to one year, subjected to condition that there will be no changes/additions/deletions in the offered property OR asset OR in market trend or purpose of valuation. 4. Any fabrication, copying, or distribution of the parts of this NDT report or any action or omission carried out by any outsider with malafied intention is prohibited and will be unlawful.



स्वास्थ्य एवं परिवार कल्याण मंत्रालय के तहत सहायक विभाग
Statutory Body under the Ministry of Health & Family Welfare

List of State Nursing Council Recognised Institutions offering Various Programmes Inspected Under Section 13 and 14 of INC Act Found Suitable for the Academic Year 2024-2025.

31 Dec 2024

Sl.No.	Institution Name & Address	Trust Name	District Name	Sector	Programme	Annual Intake
1694	College Of Nursing, Afmc Wanowarie, Vill.-, Tehsil- Haveli, Distt.- Pune, Pin Code- 411040	Armed Forces	Pune	Government	P B B.Sc(N) Post Basic Diploma in Cardio Thoracic Nursing Post Basic Diploma in Operation Room Nursing	20 (Twenty) 8 (Eight) 20 (Twenty)
1695	College Of Nursing, Gmc, Aurangabad, Distt.- Aurangabad, Pin Code- 431001	Government Of Maharashtra	Aurangabad	Government	M. Sc (N) B.Sc(N)	20 (Twenty) Med-Surg-6 Psy-2 Chn-4 Paed-4 Obg-4 50 (Fifty)
1696	College Of Nursing, Government Medical College And Hospital, Ajni, Vill.-, Tehsil- Nagpur(Urban)1&2, Distt.- Nagpur, Pin Code- 440003	Government Medical College And Hospital, Nagpur	Nagpur	Government	B.Sc(N)	50 (Fifty)

GOVERNMENT OF MAHARASHTRA
OFFICE OF THE EXECUTIVE ENGINEER
PW Division, Chhatrapati Sambhaji nagar

121957230

États-Unis - 2000 - 470

WORK ORDER

100

W10 SCRAPES.
Pop-A10 ZSCRAPES.
SHOPS NO 05 OFF BING
E 0511 0105010000000000

DEMOLITION OF NURSES COLLEGE AND ANIMAL HOUSE BUILDING AT GOVT MEDICAL COLLEGE

AND HOSPITAL, CHH SAMBHAJINAGAR

Techniques of the World War II

A Young Tenthredinid Orestion on North Carolina's Outer Banks

© The Journal of the Philosophy of Education Society of Great Britain 2006.

[illegible]

5 Your Office letterfile file will need 1399-2-2095

This office has received notification of the initial Security Deposit Rs. 666/- (Rs. Six hundred and 66/-) in the form of DD No. 5626995 Dtd. 13-01-2025 of SRI BALAKRISHNAN SHANMUGARAJU for Rs. 6,000/- (Six thousand) valid for period from 13-01-2025 to 13-04-2025 for your notice registration after for the above work of SUEqual fee estimated cost of Rs. 2,72,227,000/- (Rs. Twenty two Lakhs twenty two thousand and twenty two) only out to tender is hereby accepted on behalf of the Government of Maharashtra. The accepted rate is 0% Equal the contract cost of Rs. 2,22,223,000/-

Your attention is also directed to the fact that any inquiry regarding Policy 2.0 is to be directed to the Department of Personnel.

As the world's largest supplier of property and casualty insurance, we have the resources and expertise to help you protect your business and your future.

You are also entitled to furnish a written statement of your position if you wish. If you do not wish to do so, you must so indicate. If you do not wish to do so, you must so indicate.

You wonder how the work was accepted sooner, that happens after he is paid as the second department in 1933-1935.

You are therefore requested to sign the following declaration with the Sub-District Engineer, PW (Civil) Sub-Division No. 1, Cultural Heritage Management, who is working at the same station, to be submitted with 01 Calendar Month's delay between the date period is 15 calendar months.

Scand. J. Psychol. 1997, 38, 1-12



PAN No : ABRPRIDEIP
20250913153710YUNJEXUSKWF85VZUJPI0
08CNO-04131029-010101174-028

Executive Engineer
Pw Division, Chhatrapati Sambharam

This is system generated work order. Please do not assign signature from the assigned officer.

- 1) Copy submitted to the Accountant General, Maharashtra for information please
- 2) Copy submitted to the Directorate of Insurance for information please
- 3) Copy submitted to the Labour Commissioner (District Labour Office) for information please
- 4) Copy submitted to the Superintending Engineer, P. W. Circle, Chavangan, Sangli, for information please
- 5) Copy submitted to Superintending Engineer, Water and Electricity, Chavangan, Sangli, for information please
- 6) Copy forwarded to the Sub-Divisional Engineer, P. W. Circle (Sub-Division No. 1, Chavangan) Sangli, for information and necessary action
- 7) Copy to be placed in Electrical Office for information and necessary action